EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	348921	steer\$4	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/03/12 11:09
L2	13270	1 and (yoke)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/03/12 11:08
L3	191	2 and (bobbin)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/03/12 11:09
L4	77	3 and (terminal)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/03/12 11:09
L5	29	4 and (pin)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/03/12 11:09
L6	28	5 and (sens\$4 detect\$4 transducer measur\$4 gage gauge cell)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR _.	ON	2007/03/12 11:08
L7	13	6 and (conductive conducting)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/03/12 11:09
L8	6	7 and (resin mold\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/03/12 11:09
L9	54891	(torque) near3 (sens\$4 detect\$4 transducer measur\$4 gage gauge cell)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/03/12 11:08

EAST Search History

L10	1773	9 and (yoke)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/03/12 11:08
L11	151	10 and (bobbin)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/03/12 11:10
L12	4 5	11 and (conductive conducting)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/03/12 11:09
L13	17	12 and (pin)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/03/12 11:09
L14	. 12	13 and (terminal)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/03/12 11:09
L15	8	14 and (resin mold\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/03/12 11:09
L16	3	15 and (steer\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/03/12 11:10

3/12/07 11:12:58 AM Page 2